

This is an Agreement between you, the undersigned Client, and us, the Inspector, pertaining to our inspection of the Property listed below.

The terms below govern this Home Inspection Agreement.

1. The inspection fee is \$ Add	ress: SAMPLE
2. We will perform a visual inspection of the home and (2) deemed material. The report is only sup	e/building and provide you with a written report identifying the defects that we (1) observed plementary to the seller's disclosure.
not test for mold. We will not test for complianc the presence of asbestos, lead paint, soil contam to inspect is inaccessible, you understand that suc will NOT include inaccessible areas in their ent	NOT test for the presence of radon, a harmful gas. Unless otherwise indicated in writing, we will be with applicable building codes or for the presence of or for any potential dangers arising from an ination, or other environmental hazards or violations. If any part of the structure you want us ch structures are impossible for us to inspect and evaluate. Therefore, the scope of our inspection tirety. Insight Home Inspections is not responsible in any capacity for any repairs that need by the homeowner: Chinese Drywall, Lead Paint or Asbestos.
persons, or other interested parties. You will be th by third parties, and third parties who rely on it from any liability whatsoever. If you or any pers release us from any liability and agree to pay our a guarantee or warranty, expressed or implied,	nly. You give us permission to discuss our observations with real estate agents, owners, repair ne sole owner of the report and all rights to it. We are not responsible for use or misinterpretation in any way do so at their own risk and release us (including employees and business entities) son acting on your behalf provide the report to a third party who then sues you and/or us, you costs and legal fees in defending any action naming us. Our inspection and report are in no way regarding the future use, operability, habitability or suitability of the home/building or its ed or implied, to the fullest extent allowed by law.
liability is limited to liquidated damages in an ar special, or incidental damages or for the loss of th that we intend it to: (i) reflect the fact that actual	or replacement of unreported defects, either current or arising in the future. In all cases, our mount not greater than the fee you paid us. You waive any claim for consequential, exemplary, he use of the home/building. You acknowledge that this liquidated damages is not a penalty, but damages may be difficult or impractical to ascertain; (ii) allocate risk between us; and (iii) enable fee. It is agreed and understood that we will not be held liable for any errors and omissions in the
	al, plumbing, or any other job function requiring an occupational license in the jurisdiction e-inspection, the re-inspection is subject to the terms of this Agreement.
	gation arising out of this Agreement shall be in the county where we have our principal place of you agree to pay all our legal costs, expenses and attorney's fees incurred in defending that claim.
agreement; there are no terms other than those s by us shall be binding unless reduced to writing a writing and signed by you and by one of our author	ent invalid, the remaining provisions remain in effect. This Agreement represents our entire set forth herein. All prior discussions are merged into this Agreement. No statement or promise nd signed by one of our authorized officers. Any modification of this Agreement must be in orized officers. This Agreement shall be binding upon and enforceable by the parties and their issignees. You will have no cause of action against us after the inspection is preformed /
	iguous or requiring judicial interpretation, the court shall not construe that term against us by ent is construed against the party drafting it. You had the opportunity to consult qualified
	ng on behalf of all of them, and you represent that you are authorized to do so. t(s) to the above terms & conditions regardless of whether or not a signature is present on this
I HAVE CAREFULLY READ THIS AGREEMENT. I A	GREE TO IT AND ACKNOWLEDGE RECEIVING A COPY OF IT.
Client:	Email
Inspector: Michael Strano	License #HI9693

Insight Home Inspections, LLC.

www.insighthomeinspections.biz

561.252.5202 IHI.Strano@Gmail.com

HOME INSPECTION REPORT

Inspection Time: 9:00am Description of Home
Single Family X
Town House
Villa
Condo
Duplex
Configuration:
Home occupied at time of inspection: Yes X No No
Year Built: 2013
Total Square Feet:
Date of Last Significant Rainfall: >1 week < 1 weekX
Comments:



	Home Inspection Report	N	S	U	R	c
١,		0	A	N	E	_
1		T	T	S	P	F
E			ı	Α	Α	E
N		Α	S	Т	ı	Т
	GROUNDS	P	F	I	R	Y
		P	Α	S		E T Y I S S U E
		L	C T	F A	N E	-
		c	0	c	E	_
		Α	R	T	D	Ū
	Note: This inspection is not a warranty and/or guarantee. Building codes are not applicable in this	В	Υ	0	E	E
	inspection report.	L		R	D	
		E		Υ		
	Walkways			Х	Х	
2	·			Х	Х	
3	Porch		X			
4				X	X	
5	Stoops /Steps		X			
6	Deck / Balcony		X			
7	Fence / Wall		X			
8	Overhanging Trees			Х	Х	
g	Landscaping Effecting Foundation		Х			
1	D Low Spots / Standing Water		Х			
1	1 Storm Water Runoff		Χ			
1	2 Hose Bibs		Χ			
1	3 Drain Line(s)		Χ			
	COMMITAITC					

- 1 & 2. Cracked, Damaged & Uneven pavers noted on Walkways & Driveway.
- 4. Damaged stone pavers noted around pool area.
- 8. Overhanging trees noted on left side of dwelling / making contact with roof.



	Home Inspection Report	N.				•
١,		N O	S A	U N	R E	S A
Ť		Т	T	S	P	F
E			1	Α	Α	E
М		Α	S	T	- 1	T
	<u>EXTERIOR</u>	P	F	ı	R	Y
		P L	A C	S F	N	
		ī	T	A	E	s
		С	0	C	Ε	S
	Note: This inspection is not a warranty and/or guarantee. Building codes are not applicable in this	Α	R	T	D	U
	inspection report.	В	Υ	0	E D	E
	inspession reports	E		R Y	D	
	Note: Aluminum windows have a usable life of approximately 20 years.			•		
1	Siding Condition:			Х	Х	
2	Caulking Around Doors / Windows		X			
3	Ground Clearance with Siding		X			
4	Trim		X			
5	Doors			X	X	
6	Walls		X			
7	Windows		X			
8	Electrical Receptacles, GFI installed: Yes X No			Χ	Х	
	Lighting		X			
_	Water Supply Piping Material Installed: Copper_X PVC_X PolybutyleneOther		X			
	Main Water Supply Shut-Off Valve		X			
12	Evidence of Main Water Supply Leak		X			
	Foundation Type: Slab on Grade X Wood Visible: Yes No X Chimney(s) Type: Masonry X Metal Visible: Yes X No Visible: Yes		Х			
			X			
	Pool /Cabana			X	X	Х
16	Screen Enclosure	X				

- 1. Damaged siding noted entry sides of garage(left side garage door).
- 1. Settling cracks & previous repairs noted on siding / rear of dwelling.
- 5. Right side(from interior view) French Door lock mechanism is not functioning (does not unlock) / Front Door.
- 8. Exposed & damaged electrical lighting wire noted (low voltage) / right side of dwelling (by Generac unit).
- 15. Damaged stonework noted around pool & jacuzzi / sharp edges detected.
- 15. Pool lighting fixture appears to be loose & separating from wall(inside pool).







Siding Damage

Settling Crack







Settling Cracks

Previous Repair







Lock Mechanism

Damaged/Split line.







Light Fixture

Jacuzzi







Pool Heater (just for reference)



Pool Light Fixture

Page 5 of 17

	Home Inspection Benert					
	Home Inspection Report	N	S	U	R	S
I		0	Α	N	E	Α
T E		Т	T	S	P	F E
M		Α	I S	A T	A I	T
'''	BATHROOMS	P	F	i	R	Y
	<u>DATTINO OTTIS</u>	Р	Α	S		
		L	С	F	N	-1
		ı	T	Α	E	S
		C A	O R	C T	E D	S U
		В	Υ	0	E	E
	Note: This inspection is not a warranty and/or guarantee. If the home is occupied at the time of the	L		R	D	
	inspection, some areas may not be accessible for inspection.	Ε		Υ		
1	Sinks			Х	Х	
2	Toilets		X			
3	Bathtubs		X			
4	Showers		X			
5	Evidence of Water leaks		X			
6	Ventilation Fans		X			
7	Electrical Receptacles, GFCI installed: Yes X No		X			
8	Lighting		X			
9	Water Temperature Adequate (hot)		X			
	Water Pressure / Temperature Adequate		X			
11	Drain Piping Size / Material		X			
12	Drain Rate Adequate		X			
13	Drain Traps in Place		X			
14	Ceiling / Wall(s)		Х			
15	Tile / Caulking / Grout		Х			
16	Water Hammering Issue		Х			
17	Cabinet(s) / Door			X	X	

- 1. Cold side faucet handle not installed properly / Guest Suite 1st Floor.
- 17. Lock mechanism is damaged / not functioning / Half Bathroom 1st Floor.





	Home Inspection Report					
1		N O	S A	U N	R E	S A
T		Т	T	S	P	F
E			ı	Α	Α	E
М		A P	S F	T	I R	T Y
	<u>KITCHEN</u>	P	A	S	ĸ	'
		L	С	F	N	ı
		Ι	T	Α	E	S
		C A	O R	C T	E D	S U
		В	Υ	0	E	E
	Note: This inspection is not a warranty and/or guarantee. If the home is occupied at the time of the	L	-	R	D	
	inspection some areas may not be accessible for inspection.	E		Y		
1	Cabinets		Х			
2	Countertops		Х			
3	Sink		X			
	Drain Piping		X			
	Drain Rate		X			
	Drain Traps in Place		X			
	Garbage Disposal		X			
	Evidence of Water Leakage		X			
	Water Supply Pressure		Х			
	Stove / Range		Х			
	Range Hood / Vent		Х			
_	Refrigerator		X			
	Dishwasher		X			
	Microwave		X			
	Lighting		X			
	Electrical Receptacles, GFI installed: Yes <u>X</u> No		X			
17	Ceiling		Х			
18	Wall		Х			
19	Floor / Kick Plates			X	Х	

19. Damaged flooring noted by sink cabinet.



_						
	Home Inspection Report	N	S	U	R	s
1		0	Α	N	Ε	Α
Т		Т	Т	S	P	F
E			ı	Α	Α	E
M	INITEDIOD DOOMS	Α	S	T	ı	T
	<u>INTERIOR ROOMS</u>	Р	F	ı	R	Υ
		P	A C	S F	N	
		ī	T	A	E	S
		c	0	C	E	S
		Α	R	T	D	Ū
	Notes This inspection is not a warrantee and/or guarantee. If the home is accomised at the time of the	В	Υ	0	Ε	E
	Note: This inspection is not a warrantee and/or guarantee. If the home is occupied at the time of the	L		R	D	
	inspection, some areas may not be accessible for inspection.	Ε		Υ		
1	Wall		Х			
2	Ceiling			Χ	Х	
3	Ceiling Fans		Χ			
4	Floor		Χ			
5	Molding / Trim		X			
6	Doors		X			
7	Lighting		X			
8	Electrical Receptacles		X			
9	Smoke Detectors		X			
10	Stairs & Railings		X			
11	Attic Access Type: Hatch <u>X</u> Ladder <u> </u>		X			

2. Previous repair noted on ceiling above TV / Den(off kitchen area).









Multiple areas tested for moisture intrusion / No moisture detected at time of inspection

			ı			
	Home Inspection Report	N	s	U	R	s
1		0	A	N	E	A
Т		T	Т	S	Р	F
E			ı	Α	Α	Ε
M		Α	S	Т	I	Т
	GARAGE / LAUNDRY ROOM	P	F	ı	R	Υ
		P L	A C	S F	N	
		ì	Т	A	E	S
		C	0	С	E	S
		Α	R	Т	D	U
	Note: This inspection is not a warranty and/or guarantee. If the home is occupied at the time of the	В	Υ	0	Е	E
	inspection some areas may not be accessible for inspection.	L		R	D	
	inspection some areas may not be accessible for inspection.	E		Y		
1	Automatic Opener		Х			
2	Garage Door		Х			
3	Wash Tub		X			
4	Washer		X			
5	Dryer		X			
6	Dryer Venting Properly		X			
7	Interior Service Door		X			
8	Exterior Door	X				
9	Lighting		X			
10	Ceiling		X			
11	Floor		X			
12	Wall		Х			
13	Electrical Receptacles		Х			
14	Carport	X				
	COMMANDE.					

	Home Inspection Report	N	S	U	R	s
1		О	Α	N	Ε	Α
Т		Т	Т	S	Р	F
Ε			1	Α	Α	Ε
М	<u>INSULATION</u>	Α	S	Т	1	Т
		Р	F	1	R	Υ
		Р	Α	S		
		L	С	F	N	- 1
		ı	Т	Α	Ε	S
		С	0	С	Ε	S
	Note: This inspection is not a warranty and/or guarantee. Due to limited attic clearance, not all areas may	Α	R	Т	D	U
	be accessible for inspection. Building codes are not applicable in this inspection report.	В	Υ	0	E	E
		L		R	D	
_		E		Y		
	Attic Insulation Type & Coverage: Blown RolledOther _X		X			
	Attic Hatch Insulation installed: Yes No _X		Х			
3	Attic Ventilation Adequate		Х			
4	Vapor Barrier Condition (if accessible)	Х				
5	Multi Pane Windows installed: Yes X No		Х			
6	Door & Window Weather-stripping Condition		Х			
7	Electrical		Х			
					-	
-						

COMMENTS: * limited inspection due to Spray foam being utilized to insulate attic area*





Page 10 of 17

	Home Inspection Report				_	_
١.		N O	S A	U	R	S
		T	T	S	P	F
E		•	·	A	A	E
М	HEATING & COOLING	Α	S	Т	ı	Т
		P	F	ı	R	Υ
		P	Α	S		
		L	C	F	N	ı
	Note: This inspection is not a warranty and/or guarantee. Due to limited attic clearance, not all areas may	C	T O	A C	E	S
	be accessible for inspection. Building codes are not applicable in this inspection report.	A	R	T	D	U
	be accessible for inspection, building codes are not applicable in this inspection report.	В	Υ	0	E	E
	Note: Central A/C systems have a life expectancy of approximately 15 years and water heaters 12 years.	L		R	D	
	indee. Central Ay 6 systems have a line expectancy of approximately 15 years and water neaters 12 years.	Ε		Υ		
1	HVAC System Type: Wall mount Central A/C _X System Age: 7 Yr(s).		Х			
	Cooling Ability:		Х			
_	Heating Ability:		Х			
	HVAC Compressor if accessible		Х			
	HVAC Compressed Freon Line Insulation if accessible		^	Х	х	
	HVAC Compressor Ventilation (clear of bushes etc.) if accessible		Х	^	^	
	HVAC Air Handler if accessible		X			
-	HVAC Air Handler Drain Clear if accessible		X			
_	HVAC Ductwork if accessible		X			
	Thermostat		X			
-	Water Heater Relief Valve Venting Properly		X			
12	Water Heater Condition		X			
	COMMENTS: *Coo booder notes for details on system life expectancy					

COMMENTS: *See header notes for details on system life expectancy.

AC systems were operating at 18 & 20 & degree differential(s)...15 to 20 degrees is optimal.

8. AC compressor freon line insulation is deteriorating (unit #2 left side dwelling) / Needs to be replaced.
























Damaged Freon Line Insulation













Insight Home Inspections, LLC.
























	Home Inspection Report	N	s	U	R	S
I T E M	ROOF	NOT APPLICAB	S A T I S F A C T O R Y	UNSATISFACTO	R E P A I R N E E D E	S A F E T Y I S S U E
	Note: This is NOT a "code" inspection. This inspection is for water-tightness only. Due to limited attic clearance, not all areas may be accessible for inspection.	L E		R Y	D	
1	Roof Material: Cement TileBarrel TileX_Tar & Gravel Cedar ShakeStrip ShingleOtherX_		Х			
2	Roof Properly Installed		Х			
3	Missing Shingles and/or Tiles		X			
	Shingle Blisters or Curled	X				
	Cracked Tiles			X	X	
6	Moss or Mildew		X			
	Flashing		X			
	Fascia		Χ			
	Soffits and Vent Screens			X	X	
	Ventilation Clear and adequate		X			
	Cracks or Gaps in Roofing			X	X	
12	Evidence of Leaks		X			
13	Skylights	Х				
14	Gutters & Downspouts			Х	Х	
15	Vent Pipes		Х			
16	Low Spots on Roof		Х			
17	Roof Sheathing	Х				

- 5. Cracked tiles & previous repairs noted. Further evaluation by a licensed roofer needed.
- 9. Damaged soffit noted / left side of dwelling by AC units. Further evaluation by a licensed roofer needed.
- 11. Deteriorated flat surface as well as previous repairs noted. Further evaluation by a licensed roofer needed.
- 14. Debris noted in gutters / multiple locations. Needs to be removed.
- 14. Downspout needs to be extended to runoff / currently expelling onto flat roof. Further evaluation by a licensed roofer needed.
- 14. Damaged downspout noted / left side of dwelling.







Insight Home Inspections, LLC.







Soffit













Re-direct to runoff

Damaged

	Home Inspection Report					
1		N O	S A	U N	R E	S A
'		T	T	S	P	F
E		•	i	A	A	E
М		Α	S	Т	ı	Т
	ELECTRICAL	P	F	ı	R	Υ
		P	Α	S		
		ı	C T	F A	N E	I S
		Ċ	0	Ĉ	E	S
		Α	R	Т	D	U
	Note: This inspection is not a warranty and/or guarantee. Building codes are not applicable in this	В	Υ	0	Ε	E
	inspection report.	L		R	D	
		Е		Υ		
1	Main Power Amperage: 400 / 200 Amp(s)		Х			
2	Circuits Clearly Labeled		Х			
3	GFCI Breakers		X			
4	AFCI Breakers		X			
5	Circuit Panel Accessible		X			
6	Appears Grounded to Earth		X			
7	Overhead Wiring Clearances		X			
8	Overhead Supply Line Mast		X			
9	Main Circuit Panel Condition		X			
	Exterior Service Condition		X			
11	Double Taps: Yes No _X		X			
12	Hazardous Panel: Yes No _X		X			

















Insight Home Inspections, LLC.

www.insighthomeinspections.biz

561.252.5202 IHI.Strano@Gmail.com

Page 17 of 17