

This is an Agreement between you, the undersigned Client, and us, the Inspector, pertaining to our inspection of the Property listed below.

The terms below govern this Home Inspection Agreement.

| 1. The inspection fee is $$0.00$ | Address: |
|---|--|
| | f the home/building and provide you with a written report identifying the defects that we (1) observed sonly supplementary to the seller's disclosure. |
| not test for mold. We will not test for of the presence of asbestos, lead paint, so to inspect is inaccessible, you understar will NOT include inaccessible areas in | s, we will NOT test for the presence of radon, a harmful gas. Unless otherwise indicated in writing, we will compliance with applicable building codes or for the presence of or for any potential dangers arising from oil contamination, or other environmental hazards or violations. If any part of the structure you want us not that such structures are impossible for us to inspect and evaluate. Therefore, the scope of our inspection their entirety. Insight Home Inspections is not responsible in any capacity for any repairs that need authorized by the homeowner: Chinese Drywall, Lead Paint or Asbestos. |
| persons, or other interested parties. You by third parties, and third parties wh entities) from any liability whatsoeve us, you release us from any liability an no way a guarantee or warranty, expres | our use only. You give us permission to discuss our observations with real estate agents, owners, repair u will be the sole owner of the report and all rights to it. We are not responsible for use or misinterpretation to rely on it in any way do so at their own risk and release us (including employees and business r. If you or any person acting on your behalf provide the report to a third party who then sues you and/or dagree to pay our costs and legal fees in defending any action naming us. Our inspection and report are in so or implied, regarding the future use, operability, habitability or suitability of the home/building or its s, express or implied, to the fullest extent allowed by law. |
| liability is limited to liquidated damag special or incidental damages or for th that we intend it to: (i) reflect the fact tl | of repair or replacement of unreported defects, either current or arising in the future. In all cases, our ges in an amount not greater than the fee you paid us. You waive any claim for consequential, exemplary, he loss of the use of the home/building. You acknowledge that this liquidated damages is not a penalty, but hat actual damages may be difficult or impractical to ascertain; (ii) allocate risk between us; and (iii) enable reed-upon fee. It is agreed and understood that we will not be held liable for any errors and omissions in the |
| | rchitectural, plumbing, or any other job function requiring an occupational license in the jurisdiction equest a re-inspection, the re-inspection is subject to the terms of this Agreement. |
| | or any litigation arising out of this Agreement shall be in the county where we have our principal place of a against us, you agree to pay all our legal costs, expenses and attorney's fees incurred in defending that |
| agreement; there are no terms other th by us shall be binding unless reduced t writing and signed by you and by one of | is Agreement invalid, the remaining provisions remain in effect. This Agreement represents our entire an those set forth herein. All prior discussions are merged into this Agreement. No statement or promise o writing and signed by one of our authorized officers. Any modification of this Agreement must be in our authorized officers. This Agreement shall be binding upon and enforceable by the parties and their stors, and assignees. You will have no cause of action against us after the inspection is preformed / |
| | ment ambiguous or requiring judicial interpretation, the court shall not construe that term against us by a document is construed against the party drafting it. You had the opportunity to consult qualified |
| | are signing on behalf of all of them, and you represent that you are authorized to do so. the client(s) to the above terms & conditions regardless of whether or not a signature is present on this |
| I HAVE CAREFULLY READ THIS AGREEM | MENT. I AGREE TO IT AND ACKNOWLEDGE RECEIVING A COPY OF IT. |
| Client: | Email |
| Girent. | Lindii |
| Inspector: Michael Strano | License #HI9693 |

Insight Home Inspections, LLC.

www.insighthomeinspections.biz

561.252.5202 IHI.Strano@Gmail.com

HOME INSPECTION REPORT

| Inspection Time: 12:00pm Description of Home |
|---|
| Single Family X |
| Town House |
| Villa |
| Condo |
| Duplex |
| Configuration: |
| Home occupied at time of inspection: Yes NoX |
| Year Built: 2019 |
| Total Square Feet: 3,696 |
| Evidence of Renovations: Yes NoX (if "Yes", building permits should be checked) |
| Date of Last Significant Rainfall: >1 week < 1 week X |
| Comments: |



| | Home a least action Bone et | | | | | |
|----|---|--------|---|--------|--------|--------|
| | Home Inspection Report | N | S | U | R | S |
| I | | 0 | Α | N | E | Α |
| Т | | T | Т | S | P | F |
| E | | | ı | A | A | E T |
| М | GROUNDS | A P | S | T | l R | Y |
| | GROUNDS | P | A | S | " | • |
| | | L | С | F | N | 1 |
| | | 1 | Т | Α | E | S |
| | | С | 0 | С | E | S |
| | | Α | R | T | D | U |
| | Note: This inspection is not a warranty and/or guarantee. Building codes are not applicable in this | В | Y | O R | E D | E |
| | inspection report. | E | | Y | | |
| 1 | Walkways | | Х | | | |
| 2 | Driveways | | X | | | |
| 3 | Porch | | X | | | |
| 4 | Patio | | X | | | |
| 5 | Stoops /Steps | | X | | | |
| 6 | Deck / Balcony | X | | | | |
| 7 | Fence / Wall | X | | | | |
| 8 | Overhanging Trees | | Х | | | |
| 9 | Landscaping Effecting Foundation | | X | | | |
| 10 | Low Spots / Standing Water | | X | | | |
| 11 | Storm Water Runoff | | X | | | |
| 12 | Hose Bibs | | X | | | |
| 13 | Drain Line(s) | | X | | | |
| , | CONANAENTC: | | | | | |

| _ | | | | | l 1 | |
|------------------|--|---------------------------|-------------------------|-----------------------------|--|---|
| I T E M | Home Inspection Report EXTERIOR Note: This inspection is not a warranty and/or guarantee. Building codes are not applicable in this inspection report. Note: Aluminum windows have a usable life of approximately 20 years. | N O T A P P L I C A B L E | S A T I S F A C T O R Y | U N S A T I S F A C T O R Y | R E P A I R N E E D E D | S A F E T Y I S S U E |
| 1 | Siding Condition: | | Х | | | |
| 2 | Caulking Around Doors / Windows | | Х | | | |
| 3 | Ground Clearance with Siding | | Х | | | |
| 4 | Trim | | X | | | |
| 5 | Doors | | | Х | Х | |
| 6 | Walls | | X | | | |
| 7 | Windows | | X | | | |
| _ | Electrical Receptacles, GFI installed: Yes X No | | X | | | |
| | Lighting | | X | | | |
| | Water Supply Piping Material Installed: Copper_X PVC_X PolybutyleneOther | | X | | | |
| | Main Water Supply Shut-Off Valve | | X | | | |
| 12 | Evidence of Main Water Supply Leak | | X | | | |
| 13 | Foundation Type: Slab on Grade X Wood Visible: Yes No X No X | | X | | | |
| 14 | Chimney(s) Type: Masonry Metal Visible: Yes NoX | X | | | | |
| 15 | Pool /Cabana | Х | | | | _ |
| | | | | | | |

5. Rear sliding doors not sealed/caulked properly. Needs to be sealed to prevent water intrusion.







| | Home Inspection Report | N | S | U | R | s |
|----|--|---|--------|--------|--------|---|
| 1 | , | 0 | A | N | E | A |
| T | | Т | T | S | P | F |
| E | | | 1 | Α | Α | E |
| M | | Α | S | Т | ı | Т |
| | BATHROOMS | Р | F | I | R | Υ |
| | | P | A | S F | | |
| | | L | C T | A | N E | S |
| | | c | 0 | c | E | S |
| | | Α | R | Т | D | U |
| | Note: This inspection is not a warranty and/or guarantee. If the home is occupied at the time of the | В | Υ | 0 | E | E |
| | inspection, some areas may not be accessible for inspection. | L | | R | D | |
| | | E | | Υ | | |
| 1 | Sinks | | X | | | |
| 2 | Toilets | | X | | | |
| 3 | Bathtubs | | X | | | |
| 4 | Showers | | | X | Х | X |
| 5 | Evidence of Water leaks | | X | | | |
| 6 | Ventilation Fans | | X | | | |
| 7 | Electrical Receptacles, GFCI installed: Yes <u>X</u> No <u></u> | | X | | | |
| 8 | Lighting | | X | | | |
| | Water Temperature Adequate (hot) | | X | | | |
| | Water Pressure Adequate | | X | | | |
| | Drain Piping Size / Material | | X | | | |
| 12 | Drain Rate Adequate | | X | | | |
| 13 | Drain Traps in Place | | X | | | |
| 14 | Ceiling / Wall(s) | | X | | | |
| 15 | Tile / Caulking / Grout | | X | | | |
| | Water Hammering Issue | | X | | | |
| 17 | Cabinet(s) / Door | | X | | | |
| (| COMMENTS: | | | | | |

4. Glass shower door making contact with shower head & towel bar / Master Bathroom.





| _ | , | | | | | |
|------------------|---|---------------------------|-------------------------|-----------------------------|---------------|---|
| I T E M | Home Inspection Report KITCHEN Note: This inspection is not a warranty and/or guarantee. If the home is occupied at the time of the inspection some areas may not be accessible for inspection. | N O T A P P L I C A B L E | S A T I S F A C T O R Y | U N S A T I S F A C T O R Y | REPAIR NEEDED | S A F E T Y I S S U E |
| 1 | Cabinets | | Х | | | |
| 2 | Countertops | | Χ | | | |
| 3 | Sink | | X | | | |
| 4 | Drain Piping | | Х | | | |
| 5 | Drain Rate | | Х | | | |
| 6 | Drain Traps in Place | | X | | | |
| 7 | Garbage Disposal | | X | | | |
| | Evidence of Water Leakage | | Х | | | |
| | Water Supply Pressure | | Х | | | |
| | Stove / Range | | X | | | |
| | Range Hood / Vent | | X | | | |
| | Refrigerator | | X | | | |
| 13 | Dishwasher | | X | | | |
| 14 | Microwave | | X | | | |
| 15 | Lighting | | Х | | | |
| | Electrical Receptacles, GFI installed: Yes <u>X</u> No | | X | | | |
| 17 | Ceiling | | X | | | |
| 18 | Wall | | X | | | |
| 19 | Floor / Kick Plates | | Х | | | |
| | | | | | | |

| | | 1 | 1 | | | |
|----|---|---|--------|--------|--------|---|
| | Home Inspection Report | N | S | U | R | s |
| 1 | | О | Α | N | Ε | Α |
| Т | | Т | Т | S | Р | F |
| E | | | 1 | Α | Α | E |
| М | | Α | S | Т | 1 | Т |
| | INTERIOR ROOMS | P | F | I | R | Υ |
| | | P | A | S | | . |
| | | | C T | F A | N E | S |
| | | c | 0 | C | E | S |
| | | A | R | T | D | Ŭ |
| | | В | Υ | 0 | Е | E |
| | Note: This inspection is not a warrantee and/or guarantee. If the home is occupied at the time of the | L | | R | D | |
| | inspection, some areas may not be accessible for inspection. | Ε | | Υ | | |
| 1 | Wall | | Х | | | - |
| 2 | Ceiling | | Χ | | | |
| 3 | Ceiling Fans | | Х | | | |
| 4 | Floor | | Χ | | | |
| 5 | Molding / Trim | | X | | | |
| 6 | Doors | | X | | | |
| 7 | Lighting | | X | | | |
| 8 | Electrical Receptacles | | X | | | |
| 9 | Smoke Detectors | | X | | | |
| 10 | Stairs & Railings | | X | | | |
| | Attic Access Type: Hatch <u>X</u> Ladder <u> </u> | | X | | | |
| 12 | Windowsill(s) | | X | | | |







Multiple areas tested for moisture/ No moisture Detected at time of inspection

| I T E M | Home Inspection Report | N O T | S A T I S | U N S A T | R E P A | S A F E T |
|------------------|--|-------------|-----------------------|-----------------------|------------------|-----------------------|
| | GARAGE / LAUNDRY ROOM | Р | F | ı | R | Υ |
| | GARAGE / EAGNDRI ROOM | P | Α | S | | |
| | | L | C T | F A | N E | S |
| | | l C | 0 | C | E | S |
| | | Α | R | T | D | Ü |
| | | В | Υ | 0 | Е | E |
| | Note: This inspection is not a warranty and/or guarantee. If the home is occupied at the time of the | L | | R | D | |
| | inspection some areas may not be accessible for inspection. | Ε | | Υ | | |
| | | | | | | |
| | Automatic Opener | | X | | | |
| | Garage Door | | X | | | |
| - | Wash Tub | | X | | | |
| | Washer | | X | | | L |
| | Dryer | | X | | | |
| | Dryer Venting Properly | | Χ | | | |
| 7 | Interior Service Door | | X | | | |
| 8 | Exterior Door | X | | | | |
| | Lighting | | Χ | | | |
| | Ceiling | | X | | | |
| | Floor | | X | | | |
| 12 | Wall | | X | | | |
| 13 | Electrical Receptacles | | | Х | X | |
| 14 | Carport | X | | | | |
| | | | | | | |
| | 20.4.45.150 | | | | | |

13. Electrical outlet not installed properly(loose) / right side of electrical sub panel.





| _ | | | | - | | |
|---|---|--------|--------|--------|--------|--------|
| | Home Inspection Report | N | S | U | R | s |
| ı | | 0 | A | N | E | A |
| Т | | Т | Т | S | Р | F |
| E | | | 1 | Α | Α | Ε |
| N | INSULATION | Α | S | Т | 1 | Т |
| | | Р | F | ı | R | Υ |
| | | Р | Α | S | | |
| | | L | С | F | N | I |
| | | ı | T | A | E | S |
| | | C | O R | C T | E D | S U |
| | Note: This inspection is not a warranty and/or guarantee. Due to limited attic clearance, not all areas may | A B | Υ | 0 | E | E |
| | be accessible for inspection. Building codes are not applicable in this inspection report. | ı | ' | R | D | - |
| | | E | | Y | | |
| 1 | Attic Insulation Type & Coverage: Blown Rolled OtherX_ | | Х | | | |
| 2 | Attic Hatch Insulation installed: Yes No _X | | Х | | | |
| 3 | Attic Ventilation Adequate | | Χ | | | |
| 4 | Vapor Barrier Condition (if accessible) | Х | | | | |
| 5 | Multi Pane Windows installed: Yes X No | | X | | | |
| 6 | Door & Window Weather-stripping Condition | | Χ | | | |
| 7 | Electrical | | Χ | | | |
| | | | | | | |
| | | | | | | _ |
| | | | | | | |
| | | | | | | |
| | | | | | | |

^{*}Spray foam insulation is being utilized*







| | Home Inspection Report | N | s | U | R | s |
|----|---|--------|--------|---|---|----|
| 1 | | 0 | Α | N | E | Α |
| Т | | T | Т | S | Р | F |
| E | LIEATING Q COOLING | | 1 | Α | Α | Е |
| М | HEATING & COOLING | Α | S | T | ı | T |
| | | P P | F A | S | R | Y |
| | | Ĺ | C | F | N | ١, |
| | | ī | T | Α | E | S |
| | Note: This inspection is not a warranty and/or guarantee. Due to limited attic clearance, not all areas may | С | 0 | С | E | S |
| | be accessible for inspection. Building codes are not applicable in this inspection report. | Α | R | Т | D | U |
| | | В | Υ | 0 | E | E |
| | Note: Central A/C systems have a life expectancy of approximately 15 years and water heaters 12 years. | L E | | R | D | |
| | | E | | Y | | |
| 1 | HVAC System Type: Wall mount Central A/C _X System Age: 1 Yr(s). | | Х | | | |
| 2 | Cooling Ability: | | X | | | |
| 3 | Heating Ability: | | Х | | | |
| 4 | HVAC Compressor if accessible | | X | | | |
| 5 | HVAC Compressed Freon Line Insulation if accessible | | Χ | | | |
| 6 | HVAC Compressor Ventilation (clear of bushes etc.) if accessible | | X | | | |
| 7 | HVAC Air Handler if accessible | | X | | | |
| 8 | HVAC Air Handler Drain Clear if accessible | | X | | | |
| 9 | HVAC Ductwork if accessible | | Х | | | |
| 10 | Thermostat | | Х | | | |
| 11 | Water Heater Relief Valve Venting Properly | | Х | | | |
| _ | Water Heater Condition | | Х | | | |
| | | | | | | |
| | · · · · · · · · · · · · · · · · · · · | | | | • | |

COMMENTS: *See header notes for details on system life expectancy.

AC system(s) were operating at 19 & 20 -degree differential(s)...15 to 20 degrees are optimal.































| | Home Inspection Report | N | s | U | R | S |
|------------------|---|---------------------------------|---------------------|---------------------|-------------------|----------------------------|
| I T E M | ROOF | N O T A P L I | S A T I S F A C T O | U N S A T I S F A C | R E P A I R N E E | S A F E T Y |
| | Note: This is NOT a "code" inspection. This inspection is for water-tightness only. Due to limited attic clearance, not all areas may be accessible for inspection. | A B L E | R Y | T O R Y | D E D | E |
| 1 | Roof Material: Cement Tile X Barrel Tile Tar & Gravel Cedar Shake Strip Shingle Other | | Х | | | |
| 2 | Roof Properly Installed | | Χ | | | |
| | Missing Shingles and/or Tiles | Х | | | | |
| | Shingle Blisters or Curled | X | | | | |
| | Cracked Tiles | | | X | X | |
| | Moss or Mildew | | X | | | |
| | Flashing | | X | | | |
| | Fascia | | X | | | |
| | Soffits and Vent Screens | | X | | | |
| | Ventilation Clear and adequate | | Х | | | |
| | Cracks or Gaps in Roofing | | X | | | |
| | Evidence of Leaks | | X | | | |
| 13 | Skylights | | X | | | |
| 14 | Gutters & Downspouts | | Х | | | |
| 15 | Vent Pipes | | X | | | |
| 16 | Low Spots on Roof | | Х | | | \Box |
| 17 | Roof Sheathing | | Х | | | |
| | | | | | | |

5. Cracked tiles & previous repairs noted. Further evaluation by a licensed roofer needed.







| | Hanadan Ingara | | | | | |
|----|---|--------|--------|--------|--------|--------|
| | Home Inspection Report | N | S | U | R | S |
| 1 | | 0 | Α | N | E | Α |
| Т | | Т | Т | S | Р | F |
| E | | _ | I | Α _ | A | E |
| М | ELECTRICAL | A P | S F | T | I R | T Y |
| | <u>ELECTRICAL</u> | P | A | S | IX | • |
| | | L | С | F | N | ı |
| | | Ι | Т | Α | E | S |
| | | С | 0 | C | E | S |
| | | A | R | T | D | U |
| | Note: This inspection is not a warranty and/or guarantee. Building codes are not applicable in this | В | Υ | O R | E D | E |
| | inspection report. | E | | Y | | |
| | | _ | | - | | |
| 1 | Main Power Amperage: 200 Amp(s) | | Χ | | | |
| 2 | Circuits Clearly Labeled | | X | | | |
| 3 | GFCI Breakers | | X | | | |
| 4 | AFCI Breakers | | X | | | |
| 5 | Circuit Panel Accessible | | X | | | |
| 6 | Appears Grounded to Earth | | X | | | |
| 7 | Overhead Wiring Clearances | | X | | | |
| 8 | Overhead Supply Line Mast | | Χ | | | |
| 9 | Main Circuit Panel Condition | | Χ | | | |
| | Exterior Service Condition | | X | | | |
| 11 | Double Taps: Yes No <u>X</u> | | X | | | |
| 12 | Hazardous Panel: Yes No _X | | X | | | |













Insight Home Inspections, LLC.